Case Study CWST Relining



- Boutique hotel in central Edinburgh
- Recently extensively refurbished
- DMA Canyon requested to carry out L8 Risk Assessment




- Risk Assessment identified corroded noncompliant water tanks
- DMA Canyon advised replacement or relining of tanks which fed bars, restaurants and residents rooms (including showers)



DMA Canyon plumbing consultants attended site to investigate the options for replacing or upgrading the tanks **Issues faced:**

- External water tanks on 4th storey roof
- Poor access
- Tank replacement very costly and impractical
- Tanks linked together
- Hotel had to remain open during works



- DMA Canyon re-plumbed system to allow each on tank to be worked on individually to keep hotel operational at all times
- Other trades sub-contracted to create access to tanks and temporarily seal roof
- CWSTs re-lined whilst in-situ with a WRAS approved coating with no disruption to hotel or guests
- DMA Canyon completed plumbing remedial works and upgrade of water tanks to ensure
 L8 compliance













VAT Registration No. 743 0970 35 Company Registration No. SC197200 DMA Canyon Ltd. 14 Canyon Road, Wishaw, ML2 0EG T: 01698 536790 E: office@dmacanyon.co.uk





Successful Completion of Works – Satisfied Client

I would love to take the opportunity to thank you and your team one more time, for the brilliant job you have done at our hotel. I still cannot believe that you had to switch off the water for a few hours only, although you had to work on two tanks.

I haven't received a single complaint from the guests staying with us during the time your team was at Nira Caledonia.

I will definitely recommend your company to my colleagues and friends.

Thank you!

Carina Ratzke